PROFORMA REGARDING SAFE DRINIKING WATER AND SANITARY CONDITION CERTIFICATE

NO. Pist, Lab. MDB. 5. NO 26/23

DATE: 04/07/2023.

It is certified that an inspection team headed Raman Kumar Jha, Lab Assistant, Dist. Level Water Testing Laboratory, (Name of Officers with designation) from P.H.E.D, MADHUBANI (Name of Department/Office) inspected the Mithila Vidhyapith, Phulparas, Madhubani (Name & Address of the School) on 04/07/2023 (date of inspection) and found the Mithila Vidhyapith, (Name of School) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building and the campus as per the norms prescribed by the central/State/U.T Govt.

The above valid for a period of One Year.

Signature with Seal: ---

LAB. ASST.

Name

Designation

Name & Address of the Office/Department:

To

Mithila Vidhyapith,

Vill-Baika, Post- Mahind Bar, Via-Phulparas

DIST- Madhubani, BIHAR-847409

(Name & Address of institution)